

WeldTec®

Control Switches

These new "SS" switches are the latest advancement in torch mounted controls. They mount quickly and easily to most torch handles with convenient tie straps. They come complete with switch, cord and machine plug.

Fits...
Miller®, Lincoln®
Hobart®



WT-20 TIG torch shown with SS-5 On/Off switch.

- SWITCH SADDLE FITS MOST HANDLES
- THREE INTERCHANGEABLE SWITCHES
- SNAP ACTION CONTACTS
- NO SOLDER WIRE CONNECTIONS
- MODERN CIRCUIT BOARD DESIGN
- LOW PROFILE




Switch Assembly
Includes: Switch saddle, switch, mounting straps, cord and machine plug.

Complete Switch Assemblies


DESCRIPTION	PART NO.
Flat Top Momentary Switch, Cord and Machine Plug	SS-1F-28 X
Joy Stick Momentary Switch, Cord and Machine Plug	SS-1J-28 X
Push Button On/Off Switch, Cord and Machine Plug	SS-5-28 X

X = Plug Selection
M5 = Miller 5 Pin
M14 = Miller 14 Pin
L6 = Lincoln 6 Pin
T = Thermal Arc




Switch extension cords are available.

"SS" Series Switch Saddle



PART NO.	DESCRIPTION
SS-100	Plastic Switch Saddle Housing With Cover (Fits All Torch Handles)
SS-1F	Momentary Switch - Flat Top
SS-1J	Momentary Switch - Joy Stick
SS-5	On/Off Switch - Raised Push Button



SS-1F, SS-1J - Press and hold for contact. SS-5 - Press once for on press again for off.
All switches fit into switch saddle housing.